

Michael O. Leavitt Governor Kathleen Clarke **Executive Director** Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)



INSPECTION REPORT

Partial XXX	Complete _	Expl	oration _	
Inspection Date:	09/11/2002/	Time:	9:30-1	1:30
_	te of Last Inst			

Mine Name: Crandall Canyon Mine	County: Emery	Permit Number: <u>C/015/032</u>							
Permittee and/or Operator's Name: Genwal Resources, Inc.									
Business Address: P.O. Box 1077, Price, U	Jtah 84501								
Company Official(s): Gary Gray									
State Official(s): Karl R. Houskeeper	Fed	Federal Official(s): None							
Weather Conditions: Overcast & Misting I	Rain, Temp 64° F								
Type of Mining Activity: Underground XX	X Surface Prep	PlantOther							
Existing Acreage: Permitted 5195.8 Distu	irbed 10.7 Regrade	d Seeded							
Status: Active									

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE				
2.	SIGNS AND MARKERS	[X]		[X]	
3.	TOPSOIL				
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]		\Box	
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES				
d.	WATER MONITORING	[X]		[X]	
e.	EFFLUENT LIMITATIONS				
5.	EXPLOSIVES	[X]			[]
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box			
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS				
8.	NONCOAL WASTE	[X]			
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE	\Box			
11.	CONTEMPORANEOUS RECLAMATION				\Box
12.	BACKFILLING AND GRADING				
13.	REVEGETATION				
14.	SUBSIDENCE CONTROL				
15.	CESSATION OF OPERATIONS				[_]
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]		[X]	
b.	DRAINAGE CONTROLS				
17.	OTHER TRANSPORTATION FACILITIES	\Box			
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS				
19.	AVS CHECK (4th Quarter- April, May, June)				
20.	AIR QUALITY PERMIT				
21.	BONDING & INSURANCE	[_]			

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/015/032</u>

DATE OF INSPECTION: 09/11/2002

Date: September 11, 2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

2. SIGNS AND MARKERS

The identification sign is located at the entrance to the permit area. Observed other markers during the inspection including the disturbed area, topsoil, and stream buffer zone signs. All markers observed met the coal rules.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

A visual inspection of the sediment pond shows that the sediment and water level is still below the 60% clean marker located inside the sediment pond. The operator has scheduled the sediment pond to be cleaned next year, depending on sediment elevations.

4D. HYDROLOGIC BALANCE: WATER MONITORING

A review of the EDI website shows that first quarter 2002 information is in the pipeline. Second quarter 2002 information has not been submitted into the EDI website. This information needs to be submitted before the end of the third quarter. The water monitoring is current.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

The operator plans to chip seal the entrance road into the permit area before the onset of winter. The road is still in good shape and chip sealing the road will help to protect it from the oncoming winter conditions.

Inspector's Signature:

Karl R. Houskeeper #49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM Gary Gray, Genwal Price Field office

O:\015032.CRA\Compliance\2002\p 0911.doc